



# Hobbs Brook Dam Repairs



# Downstream Outlet







VOID BENEATH HEADWALL FOOTING TO RECEIVE UNDERWATER GROUT AND GROUT-FILLED BAGS


0+50

-A-  
PROFILE



# Upstream Gatehouse





5.  
6.  
7.  
8.  
9.

FULL DEPTH REPAIR OF MORTAR JOINTS. SEE NOTE 4 THIS SHEET (TYP)

SEE NORTH ELEVATION FOR EXTENTS OF EXTERIOR MORTAR JOINT REPAIR

SEE EAST AND WEST ELEVATIONS FOR EXTENTS OF EXTERIOR STONE MORTAR JOINT REPAIR

SEE SOUTH ELEVATION FOR EXTENTS OF EXTERIOR MORTAR JOINT REPAIR

SEE SOUTH ELEVATION FOR EXTENTS OF EXTERIOR MORTAR JOINT REPAIR

SEE SOUTH ELEVATION FOR EXTENTS OF EXTERIOR MORTAR JOINT REPAIR

SEE SOUTH ELEVATION FOR EXTENTS OF EXTERIOR MORTAR JOINT REPAIR

SEE SOUTH ELEVATION FOR EXTENTS OF EXTERIOR MORTAR JOINT REPAIR

SEE SOUTH ELEVATION FOR EXTENTS OF EXTERIOR MORTAR JOINT REPAIR

