


41


LINSKEY WAY

Mechanical roof equipment visibility



May, 2019




1A_ View from Second Street looking south




1B_ View from Second Street looking south





2A_ View from Binney Street looking west





2B_ View from Binney Street looking west




3A_ View from Linskey Way looking west




3B_ View from Linskey Way looking west



4A_ View from Linskey Way looking east



4B_View from Linskey Way looking east



5_ View from Second Street looking north